



# Parroquia de Nuestra Señora de La Concepción

Monuments — Religious monuments



## 📍 Street

Plaza de la Concepción, 10 38201  
San Cristóbal de La Laguna, Tenerife (Islas Canarias)  
Spain

## ☎ Contact

Tel 922 25 91 30

## 👤 Created by

PREDIF Técnico 3 17/09/2018

## 👤 Last modification by

PREDIF Técnico 3 17/09/2018



The accessibility of this tourism resource has been analyzed by experts

## General Information

Esta es la iglesia principal de Tenerife. La iglesia tenía una antigüedad de 500 años, pero se hundió hace varios años por el paso del tiempo. Hoy está reconstruida. Son interesantes la torre, la pila para bautizos y varias obras de arte de Fernando Estévez y Cristóbal Hernández de Quintana. La entrada accesible a la Iglesia se realiza desde la Plaza de la Concepción. Existe una serie de desniveles en la puerta de acceso debido a un pequeño escalón y al travesañ de la puerta de madera que son salvados a través de dos rampas de madera, con las siguientes dimensiones: la primera tiene una longitud de 90 cm, un ancho de 80 cm y una inclinación del 20%. La segunda tiene una longitud de 1,14 m, un ancho de 80 cm y una inclinación del 18%.

## Entrance



Entrance: Mobile ramp (available on request)

✓ Name of the tourist resource clearly visible and legible

The entranceway analysed is: The main one

Width of the entrance door: Greater than or equal to 78 cm

## Inside circulation



Wheelchair circulation: Total

Adequate lighting: No

✓ Without elements that can suppose an obstacle for a person with a visual disability

Signposting: No

## Services and amenities

Sufficient information provided about accessibility to the tourist resource : No

Adapted visits or activities for people with disabilities: No

✓ Customer service staff

### Staff training

Personal trained in attention to people with disabilities : No

Personal available to support people with specific needs: No

Personal with knowledge of Sign Language: No

## PRM Parking

- ✓ Parking lot reserved PRM

### Characteristics

Next to the establishment: Yes

Belongs to the establishment: No

Surface of the parking lot: Horizontal

Well indicated: Yes

With appropriate dimensions: Yes

## Outside areas

Sidewalks: Without obstacles

Uniform and anti-slip pavement: Yes

## Rating of establishment / place of interest

Rate 1 to 5 general accessibility of the establishment: 3 - Average

Rate 1 to 5 care you received: 4 - Good